


BMW 5 BERLINE: 1PND026

Vinnumber:	WBA5C11040D035289	Versionname:	2.0 518D (100KW)
First Registrationdate:	28/10/2013	Fiscalpower:	
Expertise Mileage:	106804	Power Kw:	100
Bodytype:	Berline	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	VS		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	HD	Sun Roof electric
Windows electric F		Central consol F
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunction		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	245/45/18/96 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1626,84
Alloy rim F L, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Crack, E - Replace		560,64



Alloy rim F R, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), Acceptable		0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R, Chemical polution, Acceptable

0,00

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

430,02

