







BMW 5: NA4051

Vinnumber: WBA5L31010G118415 First Registrationdate: 10/12/2014 Expertise Mileage: 173641 Bodytype: Break Gearbox: MAN 6 VIT Transmission: Fueltype: Diesel Battery functioning Yes Number of doors 5 Number of seats 5 Number head rests 5 Rims summer Aluminium Category Passenger Car Oil level

Versionname: 5 TOURING 520d 190PK Fiscalpower:

Power Kw: 140 Body color Dark Grey Paint type Metalic Rims summer **Aluminium** Oil level OK Parking lot 2315

Options

Radio CD Windows electric F Windows electric R Cruise Control

Steering wheel multifunctional

Seats F heated

Type of headlighting Headlighting Xenon Type of GPS GPS big screen color Type of Lining Lining leather Type of climate control **Autom climate** control Sport seats

Central consol F Luggage cover Front parking sensors Rear parking sensors

Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Sound engine	ок
Idle position	ок	Clutch test	ок
Engine startingtime	ок	Wiper fluid level	ок
Exhaust gass	ок	Lighting	ок
Transmission	ок	Wiperblades	ок
Handbrake	ок		

Degree of wear

	225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm	
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm	

Assistance equipment

Repair kit	Yes Compressor	Yes
Total cost ex VAT		982,25
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00





Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

254,16









Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00





Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)





Door R R, Scratch(es), Acceptable 0,00

No pictures to display