


**BMW 5 TOURING: 1JXU153**

Vinnumber:	<b>WBA5K31080GN99489</b>	Versionname:	<b>3.0 530D XDRIVE AUTO TOURING</b>
First Registrationdate:	<b>16/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>41880</b>	Power Kw:	<b>190</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Body color:	<b>NOIR</b>
Transmission:	<b>Back</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Maintenance:	<b>OK</b>	Oil level:	<b>OK</b>
Maintenance:	<b>6000KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric
GPS storage	<b>HD</b>	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunction		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/55/17/97 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Compressor	<b>Yes</b>
Repair kit	<b>Yes</b>		

Total cost ex VAT	698,32
Wing F R, Stone chip(s), Acceptable	0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Rocker panel inner R R, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Stone chip(s), P - Check 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00



Wing R R, Scratch(es), Acceptable 0,00



Internal Boot Lining R, Scratch(es), Acceptable 0,00



Boot cover, Scratch(es), Acceptable 0,00

