


BMW 3: 1FVQ345

Vinnumber:	WBA3D91080J219610	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	8/11/2013	Fiscalpower:	
Expertise Mileage:	91593	Power Kw:	85
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1610
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	211,80
-------------------	---------------

Wing R L, Bad repair, Acceptable	0,00
----------------------------------	-------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------

