



LEXUS GS300: 1HGF136

Vinnumber:	JTHBH1BL405002673	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	1	Power Kw:	1
Bodytype:	Berline	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	NOT OK
Battery functioning:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options

Type of headlighting:	Headlighting LED	Front parking sensors:	
Type of Lining:	Lining leather	Rear parking sensors:	

Limited Technical Inspection

Airco functioning:	NOT OK	Battery functioning:	No
Tires wear profile:	NOT OK	Sound engine:	NOT OK
Idle position:	NOT OK	Clutch test:	NOT OK
Engine startingtime:	NOT OK	Wiper fluid level:	NOT OK
Exhaust gass:	OK	Lighting:	NOT OK
Transmission:	NOT OK	Wiperblades:	NOT OK
Handbrake:	NOT OK		

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Total cost ex VAT	0,00
Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Certificate Of Conformity, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Instruction book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Bodywork, Damaged, LI - Repair and paint (complete)	0,00





Registration Document, Missing, E - Replace 0,00

No pictures to display