



**CITRO?N Jumper 33 MWB: 1FOP882**

Vinnnumber:	<b>VF7YBTMFB12450500</b>	Versionname:	<b>JUMPER 33 B/F MWB L2H1 FAP(EU5) 130PK</b>
First Registrationdate:	<b>9/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>172601</b>	Power Kw:	<b>96</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:		Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>	Parking lot:	<b>DEP 2000 476</b>
Number of doors:	<b>6</b>		
Number of seats:	<b>6</b>		
Number head rests:	<b>6</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning:	<b>NOT OK</b>	Battery functioning:	<b>No</b>
Tires wear profile:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Idle position:	<b>NOT OK</b>	Clutch test:	<b>NOT OK</b>
Engine startingtime:	<b>NOT OK</b>	Wiper fluid level:	<b>NOT OK</b>
Exhaust gass:	<b>NOT OK</b>	Lighting:	<b>NOT OK</b>
Transmission:	<b>NOT OK</b>	Wiperblades:	<b>NOT OK</b>
Handbrake:	<b>NOT OK</b>		

**Degree of wear**

	<b>215/70/15/0 R Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 2 mm</b>	Fr.R.	<b>Uniroyal: 2 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
--------------	------------	-------	------------

Total cost ex VAT	<b>558,90</b>
-------------------	---------------

Maintenance book, Missing, E - Replace	<b>0,00</b>
----------------------------------------	-------------



Certificate Of Conformity, Missing, E - Replace	<b>0,00</b>
-------------------------------------------------	-------------



Registration Document, Missing, E - Replace	<b>0,00</b>
---------------------------------------------	-------------



Wheel cover R L, Scratch(es), E - Replace	<b>22,50</b>
-------------------------------------------	--------------



Front bumper, Hole, E - Replace 398,40



Rearview mirror R complete, Scratch(es), E - Replace 138,00

