



BMW 3: 1EMR976

Vinnumber:	WBA3D910X0F404275	Versionname:	3 BER 316d 116PK
First Registrationdate:	24/01/2013	Fiscalpower:	
Expertise Mileage:	176054	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1513
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	Tow bar fixed
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Continental: 8 mm	Fr.R.	Continental: 8 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	531,88
-------------------	---------------

Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------




Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		