




BMW 3: 1FXT989			
Vinnnumber:	WBA3Y11050D447925	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	2/12/2013	Fiscalpower:	136PK
Expertise Mileage:	120910	Power Kw:	100
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2103
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		640,00	
Wing R L, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		308,20	



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Reflector, Damaged, E - Replace	25,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

