



| | | | |
|-------------------------|--------------------------|--------------|-------------------------|
| BMW 3: 1GAV787 | | | |
| Vinnumber: | WBA3D91080J412985 | Versionname: | 3 BER 316d 116PK |
| First Registrationdate: | 10/12/2013 | Fiscalpower: | |
| Expertise Mileage: | 132635 | Power Kw: | 85 |
| Bodytype: | Berline | Body color: | Beige |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1210 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | |
|--------------------------------|------------------------------|
| Options | |
| Radio CD | Central consol F |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| | 205/60/16/92 W LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

| | | | |
|------------------------------|------------|------------|---------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 423,60 |
| Roof, Bad repair, Acceptable | | | 0,00 |



| | |
|---|---------------|
| Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|





| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|--------------------------------|------|
| Bonnet, Bad repair, Acceptable | 0,00 |
|--------------------------------|------|



| | |
|----------------------------------|------|
| Tailgate, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|

