

## OPEL Zafira: 1DOF816

Vinnnumber:	<b>W0LOAHM75C2092500</b>	Versionname:	<b>ZAFIRA ecoFLEX Enjoy FAP 110PK</b>
First Registrationdate:	<b>5/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>104435</b>	Power Kw:	<b>81</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2310</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/55/16/91 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>


## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	158,00
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), PDR - Knock out without painting	63,00



Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*