



VOLKSWAGEN Golf: CJ9624			
Vinnumber:	<b>WVWZZZAUZFW019278</b>	Versionname:	<b>GOLF BER Highline 150PK</b>
First Registrationdate:	<b>4/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>110068</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1208</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
Summer tyres:	<b>225/45/17/91 Y LightMetal</b>			
	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>


Total cost ex VAT	<b>449,80</b>
Interior, Dirty, Cleaning	<b>48,00</b>



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

