



MERCEDES CLA: 1GAD561			
Vinnnumber:	WDD1173011N058573	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	4/12/2013	Fiscalpower:	
Expertise Mileage:	50227	Power Kw:	100
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1104
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		


Options	
Radio CD	Seats F L ventilated
Windows electric F	Central consol F
Windows electric R	Luggage cover
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather and alcantara
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Sound engine:	OK
Idle position:	OK	Clutch test:	OK
Engine startingtime:	OK	Wiper fluid level:	NOT OK
Exhaust gass:	OK	Lighting:	OK
Transmission:	OK	Wiperblades:	OK
Handbrake:	OK		

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment	
Repair kit:	Yes
Compressor:	Yes

Total cost ex VAT:	115,56
Front bumper, Scratch(es), It - Spot repair:	115,56



Bumper R, Bump(s), Acceptable:	0,00
--------------------------------	-------------

No pictures to display