



MERCEDES Vito: BW9756			
Vinnnumber:	WDF63960513776126	Versionname:	VITO 113 B/F 136PK Spec.LUXEMBOURG
First Registrationdate:	14/12/2012	Fiscalpower:	
Expertise Mileage:	147649	Power Kw:	100
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1207
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining artificial leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

195/65/16/100 T Steel				
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment


Spare wheel	Yes
-------------	------------

Total cost ex VAT	1518,84
Wing F R, Scratch(es), LI - Repair and paint (complete)	165,13



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Tear, E - Replace	300,00





Front bumper, Scratch(es), Smart repair 110,64



Wheel cover R R, Scratch(es), E - Replace 22,50



Interior, Incomplete, E - Replace 74,00



Trunk door R R, Bump(s) and scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 22,50



Roof, Bump(s), PDR - Knock out without painting 340,20



Trunk door R L, Scratch(es), It - Spot repair 115,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	21,60

