



RENAULT CLIO GRANDTOUR: 1FDS986

Vinnnumber:	VF17R040H49037062	Versionname:	CLIO IV BRE Expression
First Registrationdate:	3/06/2013	Fiscalpower:	75PK
Expertise Mileage:	132806	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK		
Maintenance	GEEN MELDING		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1150,32
-------------------	----------------

Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	---------------



Maintenance, Maintenance, P - Check	0,00
-------------------------------------	-------------



Door R L, Stain, Acceptable	0,00
-----------------------------	------

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	294,56
---	--------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Interior, Damaged, Acceptable	0,00
-------------------------------	------



Bumper cover R M, Scratch(es), E - Replace	590,24
--	--------



Rearview mirror housing R, Crack, Le - Replace and paint	149,96
--	--------

