


RENAULT KANGOO: 1GTK327

Vinnumber:	VF1KWX8B550757911	Versionname:	
First Registrationdate:	24/04/2014	Fiscalpower:	
Expertise Mileage:	52956	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2813
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Rear parking sensors
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining fabrics	
Type of climate control:	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	NOT OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2166,53
-------------------	---------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	122,40
-----------------------------------------------------	--------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---------------------------------------------------------------------	--------



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Front bumper, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display