


RENAULT Grand Espace: 1FHM598

Vinnnumber:	VF1JKFJC649299597	Versionname:	GR.ESPACE Initiale 149PK
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	170944	Power Kw:	110
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1119
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting Xenon	Rear parking sensors	
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/101 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1812,85
Door trim R L, Scratch(es), Smart repair	110,64



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Damaged, LI - Repair and paint (complete)	95,00
--	--------------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21

