



MERCEDES S63 AMG: 1CE0169

Vinnnumber:	WDD2173781A004376	Versionname:	
First Registrationdate:	26/11/2014	Fiscalpower:	
Expertise Mileage:	99199	Power Kw:	430
Bodytype:	Coupé	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2827
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Seats F L ventilated
Windows electric F		Seats F R ventilated
Windows electric R		Panoramic roof
Cruise Control		Central consol F
Steering wheel multifunction		Front parking sensors
Seats F heated		Rear parking sensors
Radio multimedia		Night vision
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Adaptive cruise control		
Level control		
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	255/45/19/109 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 0 mm	Fr.R.	Pirelli: 0 mm
	Re.L.	Pirelli: 0 mm	Re.R.	Pirelli: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1063,20

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), E - Replace 277,44





Alloy rim F R polished, Scratch(es), E - Replace 277,44



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), Repair/replace (lump sum) 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

