



| | | | |
|----------------------------|--------------------------|--------------|--|
| FORD S Max: 1FDS344 | | | |
| Vinnnumber: | WF0SXXGBWSDB34422 | Versionname: | S-MAX Econetic Titanium St&St DPF 115PK |
| First Registrationdate: | 3/06/2013 | Fiscalpower: | |
| Expertise Mileage: | 164658 | Power Kw: | 85 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1727 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Options | | | |
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | Tow bar removable |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 225/50/17/98 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

| | | | |
|-----------------------------|------------|------------|------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |

| | |
|--|---------------|
| Total cost ex VAT | 891,02 |
| Door R R, Bump(s), PDR - Knock out without painting | 63,00 |



| | |
|--|---------------|
| Floor covering F L, Hole, E - Replace | 264,00 |
|--|---------------|



| | |
|--|--------------|
| Wing R R, Bump(s), PDR - Knock out without painting | 63,00 |
|--|--------------|



| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------|-------|
| Interior, Dirty, Cleaning | 24,00 |
|---------------------------|-------|



| | |
|--|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Door F L, Scratch(es), LI - Repair and paint (complete) | 382,02 |
|---|--------|



| | |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display