



VOLVO V60: 1KCB300

Vinnnumber:	YV1FW8481F1266854	Versionname:	1.6 D2 KINETIC
First Registrationdate:	30/03/2015	Fiscalpower:	
Expertise Mileage:	177120	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	3		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1617,85
-------------------	----------------

Door panel R R, Damaged, E - Replace	323,71
--------------------------------------	---------------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Seat cover R, Stain, Cleaning

25,00



Door panel R L, Damaged, Smart repair

110,64



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F L, Stain, Cleaning

25,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)

211,80

