



**VOLKSWAGEN Golf: 1JEY650**

Vinnnumber:	<b>WVWZZZAUZFP570345</b>	Versionname:	<b>GOLF VAR Trendline 105PK</b>
First Registrationdate:	<b>28/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>141482</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>	Parking lot:	<b>434</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Rear parking sensors
GPS storage	<b>SD</b>	
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS base</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>No</b>
Tires wear profile	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Idle position	<b>NOT OK</b>	Clutch test	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>NOT OK</b>	Lighting	<b>NOT OK</b>
Transmission	<b>NOT OK</b>	Wiperblades	<b>NOT OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	0,00
Certificate Of Conformity, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Registration Document, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Bodywork, Damaged, LI - Repair and paint (complete)	0,00



