


SKODA Octavia: 1GDR184

Vinnumber:	TMBJG9NE8E0129118	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	9/01/2014	Fiscalpower:	105PK
Expertise Mileage:	92336	Power Kw:	77
Bodytype:		Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1628
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	393,80
-------------------	--------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rearview mirror housing L, Unclashed, N - Fit/Remove	24,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Bump(s), Acceptable 0,00



Roof pillar L, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display