



VOLKSWAGEN Transporter: 1DEL605

Vinnnumber:	WV1ZZZ7HZCH114204	Versionname:	TRANSP.1200 B/F SWB
First Registrationdate:	23/04/2012	Fiscalpower:	84PK
Expertise Mileage:	123235	Power Kw:	62
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1424
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/65/15/107 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 8 mm	Fr.R.	Bridgestone: 8 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2629,12
-------------------	----------------

Interior, Damaged, Acceptable	0,00
-------------------------------	-------------



Wing R L, Scratch(es), LI - Repair and paint (complete)	279,15
---	---------------



Front bumper, Damaged, E - Replace

398,40



Bonnet, Stone chip(s), LI - Repair and paint (complete)

313,56



Bodywork, Not original part, P - Check

0,00



Sliding door R, Bump(s), LI - Repair and paint (complete)

478,02



Bodywork, Damaged, Acceptable

0,00



Tailgate, Deformed, Le - Replace and paint

799,99



Bumper R, Damaged, E - Replace

329,40



Reflector Broken, E - Replace

30,60

