



## VOLVO V40: 1EID584

Vinnumber:	<b>YV1MV8481D2024725</b>	Versionname:	<b>V40 D2 Base 115PK</b>
First Registrationdate:	<b>11/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>140177</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2226</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining semi-leather</b>
Type of climate control:	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/55/16/91 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 3 mm</b>	Fr.R.	<b>Kleber: 3 mm</b>
	Re.L.	<b>Kleber: 3 mm</b>	Re.R.	<b>Kleber: 3 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	173,00
Door F L, Bump(s), PDR - Knock out without painting	63,00



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear roof pillar covering R, Damaged, I - Repair	110,00

