



VOLKSWAGEN Transporter: 1DEL589

Vinnnumber:	WV1ZZZ7HZCH113586	Versionname:	TRANSP.1200 B/F SWB 84PK
First Registrationdate:	23/04/2012	Fiscalpower:	
Expertise Mileage:	110368	Power Kw:	62
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2212
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 8 mm	Re.R.	Hankook: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1289,51

Boot cover, Hole, E - Replace 37,50



Interior, Damaged, Acceptable 0,00





Bodywork, Not original part, P - Check 0,00



Instrument panel complete, Crack, E - Replace 567,60



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 327,15



Bonnet, Bump(s), LI - Repair and paint (complete) 313,56



Bodywork, Damaged, Acceptable 0,00



Rearview mirror housing R, Damaged, E - Replace 43,70

