



RENAULT CLIO: 1LSY619

Vinnumber:	VF1BR2V4H45219415	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	189122	Power Kw:	55
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options

Radio CD	Luggage cover
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	NOT OK	Sound engine	NOT OK
Idle position	NOT OK	Clutch test	NOT OK
Engine startingtime	NOT OK	Wiper fluid level	NOT OK
Exhaust gass	NOT OK	Lighting	NOT OK
Transmission	NOT OK	Wiperblades	NOT OK
Handbrake	NOT OK		

Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 3 mm	Re.R.	Other: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1478,10
Registration Document, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Tyre R L, Hole, E - Replace	132,00



Floor covering F L, Hole, E - Replace	252,00
---------------------------------------	--------



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Seat cover F L, Damaged, E - Replace 360,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Certificate Of Conformity, Missing, E - Replace 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

