



RENAULT TRAFFIC: 1EBB951

Vinnumber:	VF12FL10253417563	Versionname:	TRAFFIC
First Registrationdate:	6/10/2015	Fiscalpower:	
Expertise Mileage:	101266	Power Kw:	88
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3205
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/65/16/107 T LightMetal			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	No	Jack	Yes
-------------	-----------	------	------------

Total cost ex VAT	1342,67
-------------------	----------------

Spare wheel, Missing, E - Replace	153,60
-----------------------------------	---------------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	---------------





Bumper R, Bump(s), E - Replace

329,40



Wheel cover F R, Missing, E - Replace

22,50



Engine, Maintenance, Execute

0,00

No pictures to display

Interior, Dirty, Cleaning

150,00



Bonnet, Bump(s), Acceptable

0,00



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Sliding door R, Bump(s), LI - Repair and paint (complete)

382,02




Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel arch cover F L, Broken, E - Replace

74,00



Wheel covers (all), Scratch(es), Acceptable

0,00

No pictures to display