



## VOLVO V40: 1FCS934

Vinnumber:	<b>YV1MV8481D2060894</b>	Versionname:	<b>V40 D2 Base 115PK</b>
First Registrationdate:	<b>27/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>131025</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>SERVICE IN 13811KM 9M</b>		
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

## Options

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/55/16/94 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 8 mm</b>	Fr.R.	<b>Vredestein: 8 mm</b>
	Re.L.	<b>Vredestein: 8 mm</b>	Re.R.	<b>Vredestein: 8 mm</b>

## Assistance equipment

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

Total cost ex VAT	869,33
-------------------	--------

Boot cover, Missing, E - Replace	50,00
----------------------------------	-------



Sill trim L, Strained , P - Check	0,00
-----------------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Tyre repair kit, Missing, E - Replace

210,53



Interior, Dirty, Cleaning

100,00



Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Interior, Damaged, Acceptable

0,00



Seat adjuster F L, Damaged, E - Replace

12,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R L, Strained , P - Check

0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing R R, Repaired, P - Check 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*