


AUDI A4: 1GDM424

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber: | WAUZZZ8K3EA091187 | Versionname: | A4 BER TDie 136PK |
| First Registrationdate: | 8/01/2014 | Fiscalpower: | |
| Expertise Mileage: | 100489 | Power Kw: | 100 |
| Bodytype: | Berline | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1426 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | DVD | Rear parking sensors |
| GPS storage | | |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/92 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1578,53 |
|-------------------|----------------|

| | |
|---|---------------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|---------------|



| | |
|---|---------------|
| Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

