



AUDI A4: 1FJY357

Vinnumber:	WAUZZZ8K8EN006207	Versionname:	A4 BER TDi 120PK
First Registrationdate:	22/07/2013	Fiscalpower:	
Expertise Mileage:	109877	Power Kw:	88
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK	Parking lot:	1612
Maintenance	218 DAGEN		
Maintenance	8900		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
GPS storage	Rear parking sensors
GPS storage	CD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/16/95 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	343,20
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tires, No damage, P - Check	0,00
-----------------------------	------



Wing F L, Bad repair, P - Check	0,00
---------------------------------	------



Outer backrest protection R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bad repair, P - Check 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), E - Replace 45,80



Seat F L compl, Worn, P - Check 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover R, Stain, P - Check 0,00



Bumper R, Bad repair, P - Check 0,00



Outer backrest protection L, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Damaged, E - Replace 252,00



Rearview mirror L complete, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Grill frame, Damaged, E - Replace

45,40



Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display