



AUDI A6: 1GKS894			
Vinnumber:	WAUZZZ4G1EN121443	Versionname:	A6 AVANT Quat.S-tr.204PK Aut.
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	145995	Power Kw:	150
Bodytype:	Break	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1610
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			867,21
Bonnet, Chemical polution, LI - Repair and paint (complete)			348,09



Bumper corner R L, Scratch(es), It - Spot repair	115,56
--------------------------------------------------	---------------



Bumper F L, Bump(s) and scratch(es), It - Spot repair	163,56
-------------------------------------------------------	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Windscreen, Damaged, E - Replace	0,00
----------------------------------	------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
----------------------------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Interior, Dirty, Cleaning	50,00
---------------------------	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------

