


FORD Focus: 1GDC575

Vinnumber:	WF0LXXGCBLDD25843	Versionname:	FOCUS CLIPPER Titanium
First Registrationdate:	6/01/2014	Fiscalpower:	136PK
Expertise Mileage:	127376	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Central consol F
GPS storage	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 1 mm	Fr.R.	Bridgestone: 1 mm
	Re.L.	Bridgestone: 1 mm	Re.R.	Bridgestone: 1 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	989,76
-------------------	--------

Steering wheel, Scratch(es), Acceptable	0,00
---	------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Missing, E - Replace	26,00
--------------------------------	-------



Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display


Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Reversible boot mat, Missing, E - Replace 10,00



Seat cover R L, Tear, E - Replace 360,00



Seat cover F L, Worn, Acceptable 0,00




Interior, Stain, Cleaning 75,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

