



## CITROEN C4 Picasso: 1ANV792

Vinnumber:	<b>VF7UA9HR8BJ530536</b>	Versionname:	<b>GR.C4 PICASSO 7pl.Business GPS FAP 112PK</b>
First Registrationdate:	<b>17/02/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>157442</b>	Power Kw:	<b>82</b>
Bodytype:	<b>MPV</b>	Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3124</b>
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>215/60/16/99 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1565,00</b>
-------------------	----------------

Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

No pictures to display

Tailgate, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Internal Boot Lining L, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Bump(s), LI - Repair and paint (complete) 310,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display