



BMW 5: 1EQ525

Vinnumber:	WBAMX110X0DY11442	Versionname:	5 TOURING 520dA Start/Stop 163PK aut
First Registrationdate:	20/02/2013	Fiscalpower:	
Expertise Mileage:	62614	Power Kw:	120
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1186,60
-------------------	----------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60
---	---------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

