



**BMW 5: 1FUJ012**

|                                    |                          |              |                         |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber:                         | <b>WBA5C110X0D035362</b> | Versionname: | <b>5 BER 518d 136PK</b> |
| First Registrationdate:            | <b>28/10/2013</b>        | Fiscalpower: |                         |
| Expertise Mileage:                 | <b>191617</b>            | Power Kw:    | <b>100</b>              |
| Bodytype:                          |                          | Body color:  | <b>Black</b>            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>          |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>        |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>               |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1706</b>             |
| Number of doors:                   | <b>5</b>                 |              |                         |
| Number of seats:                   | <b>5</b>                 |              |                         |
| Number head rests:                 | <b>5</b>                 |              |                         |
| Rims summer:                       | <b>Aluminium</b>         |              |                         |
| Category:                          | <b>Passenger Car</b>     |              |                         |
| Oil level:                         | <b>OK</b>                |              |                         |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                         |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| Windows electric F             |                              | Front parking sensors |
| Windows electric R             |                              | Rear parking sensors  |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Seats F heated                 |                              |                       |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining leather</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/17/97 H LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Michelin: 6 mm</b>    | Fr.R. | <b>Michelin: 6 mm</b>    |
|               | Re.L.                            | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>898,37</b> |
|-------------------|---------------|

|  |              |
|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



|   |               |
|---|---------------|
| Wing F R, Scratch(es), LI - Repair and paint (complete) | <b>264,21</b> |
|---|---------------|



|  |              |
|--|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

