


BMW 2 COUPE: 1NBL166

Vinnnumber:	WBA2G510X0V330096	Versionname:	2.0 218D (100 KW)
First Registrationdate:	12/01/2016	Fiscalpower:	
Expertise Mileage:	52752	Power Kw:	100
Bodytype:	Coupé	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3808
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Type of Tow bar	Tow bar removable
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/50/17/93 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Total cost ex VAT	452,60
Roof, Bump(s), PDR - Knock out without painting	63,00



Wing R L 3P, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R R 3P, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	82,80
---	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

