



## CITROEN Berlingo: 1GMZ845

Vinnumber:	<b>VF77B9HLOEJ528185</b>	Versionname:	<b>BERLINGO B/F Kort Fresh GPS 115PK</b>
First Registrationdate:	<b>14/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>118301</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2622</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Rear parking sensors
Windows electric F		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of GPS:	<b>GPS big screen color</b>	
Type of Lining:	<b>Lining fabrics</b>	
Type of climate control:	<b>Manual climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Kleber: 6 mm</b>	Fr.R.	<b>Kleber: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	1045,33
Wheel cover F R, Scratch(es), E - Replace	22,50



Rearview mirror housing R, Scratch(es), Smart repair	110,64
------------------------------------------------------	--------



Roof, Bump(s), LI - Repair and paint (complete)	361,13
-------------------------------------------------	--------



Trunk door R R, Bump(s) and scratch(es), It - Spot repair 115,56



Interior, Dirty, Forfeit 100,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 22,50



Wheel cover R L, Scratch(es), E - Replace 22,50



Headlight L, Deformed, Forfeit 50,00



Wheel cover R R, Scratch(es), E - Replace 22,50



Wing F L, Strained , I - Repair 48,00



Wing F L, Incomplete, E - Replace 20,00



Ignition key, Missing, E - Replace 150,00

No pictures to display