



<b>BMW 3: 1GC506</b>			
Vinnnumber:	<b>WBA3K31080F672440</b>	Versionname:	<b>3 TOURING 320dA 163PK Aut.</b>
First Registrationdate:	<b>2/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>118928</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2824</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>610,26</b>
Wing R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing F L, Scratch(es), LI - Repair and paint (complete)			<b>220,18</b>



Interior, Dirty, Forfeit	<b>100,00</b>
--------------------------	---------------



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Bumper R, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display