


BMW 4 GRAN COUPE: 1KDZ053

Vinnumber:	WBA4F11060D939129	Versionname:	2.0 420D XDRIVE (120KW) 4WD GRAN COUPE
First Registrationdate:	10/04/2015	Fiscalpower:	
Expertise Mileage:	42613	Power Kw:	120
Bodytype:		Body color	Dark Blue
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2825
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Central consol F	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/18/95 V LightMetal			
Winter tyres:	Fr.L.	Dunlop: 9 mm	Fr.R.	Dunlop: 9 mm
	Re.L.	Dunlop: 9 mm	Re.R.	Dunlop: 9 mm

Assistance equipment

 Compressor **Yes**

 Total cost ex VAT **1361,96**


 Interior, Dirty, Cleaning **100,00**


Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Scratch(es), LI - Repair and paint (complete) 577,80



Bumper moulding R, Broken, E - Replace 50,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

