


**BMW 5: 1GDC559**

Vinnumber:	<b>WBA5C31010D047234</b>	Versionname:	<b>5 BER 520d 163PK</b>
First Registrationdate:	<b>6/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>78155</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1222</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage	<b>HD</b>	Seats electric F R
GPS storage		Sun Roof electric
Windows electric F		Central consol F
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	
Head-up Display		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/55/17/101 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 2053,38

**Door R R, Scratch(es), LI - Repair and paint (complete)** 382,02

**Sill outer R, Scratch(es), LI - Repair and paint (complete)** 372,60



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 302,16



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (complete) 372,60



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16

