



**FORD C-MAX: 044BFZ**

Vinnnumber:	<b>WF0EXXGCDE9E86956</b>	Versionname:	<b>C-MAX X Trend DPF 109PK</b>
First Registrationdate:	<b>14/01/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>122459</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1225</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Luggage cover	
Windows electric F			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>NOT OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>491,80</b>
Front bumper, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Wheel cover F L, Scratch(es), E - Replace 30,00



Interior Dirty, Cleaning 100,00

interior, Dirty, Cleaning

100,00



Bonnet, Bad repair, Acceptable

0,00



Ignition key, Missing, E - Replace

150,00

*No pictures to display*

Wheel cover F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wheel cover R R, Scratch(es), Acceptable

0,00

*No pictures to display*