



<b>KIA Carens: 1FLX260</b>			
Vinnnumber:	<b>KNAHT815AE7022819</b>	Versionname:	<b>CARENS Lounge 115PK</b>
First Registrationdate:	<b>12/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>144930</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3408</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 8 mm</b>	Fr.R.	<b>Michelin: 8 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1698,50</b>
<b>Door R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>









<b>Door R R, Scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>
----------------------------------------------------------------	---------------



<b>Outer door handle F L, Scratch(es), Acceptable</b>	<b>0,00</b>
-------------------------------------------------------	-------------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	30,00
	
Wheel cover F L, Scratch(es), E - Replace	30,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00
	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	
Luggage space cover, Missing, E - Replace	240,00
