



OPEL Zafira: 1GBG819			
Vinnumber:	WOLPE9E3XE2004350	Versionname:	ZAFIRA TOURER ecoFL.Cosmo S/S 136PK
First Registrationdate:	13/12/2013	Fiscalpower:	
Expertise Mileage:	136390	Power Kw:	100
Bodytype:	MPV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2728
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/50/17/98 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	2099,05
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Dirty, Cleaning	25,00



Windscreen, Stone chip(s), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68




Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display