



LANCIA Voyager: 1GPE103			
Vinnnumber:	2C4RLAB55DR714683	Versionname:	VOYAGER Gold 178PK Aut.
First Registrationdate:	24/03/2014	Fiscalpower:	
Expertise Mileage:	196140	Power Kw:	130
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1528
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Sound engine:	OK
Idle position:	OK	Clutch test:	OK
Engine startingtime:	OK	Wiper fluid level:	OK
Exhaust gass:	OK	Lighting:	OK
Transmission:	OK	Wiperblades:	OK
Handbrake:	OK		

Degree of wear				
Winter tyres:	225/65/17/108 H LightMetal			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment	
Total cost ex VAT	1068,16
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	0,00
------------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

