



**KIA Sportage: 1GQK291**

Vinnnumber:	<b>USYPB815ADL387265</b>	Versionname:	<b>SPORTAGE 2WD Easy+</b>
First Registrationdate:	<b>1/04/2014</b>	Fiscalpower:	<b>115PK</b>
Expertise Mileage:	<b>123684</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3409</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	<b>Tow bar removable</b>
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/60/17/99 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Hankook: 5 mm</b>	Fr.R.	<b>Hankook: 5 mm</b>
	Re.L.	<b>Hankook: 5 mm</b>	Re.R.	<b>Hankook: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	1168,87
Wing trim R R, Scratch(es), E - Replace	84,00



Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Aerial, Missing, E - Replace 15,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Bumper moulding R R, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Bump(s), LI - Repair and paint (complete) 115,56



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 50,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68

