


**MERCEDES A: 1ECL968**

Vinnnumber:	<b>WDD1760121J012935</b>	Versionname:	<b>A 180 CDI BE 109PK</b>
First Registrationdate:	<b>19/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>117470</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2415</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Semperit: 4 mm</b>	Fr.R.	<b>Semperit: 4 mm</b>
	Re.L.	<b>Semperit: 6 mm</b>	Re.R.	<b>Semperit: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 331,80

Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bodywork, Not original part, Acceptable 0,00

*No pictures to display*

Interior, Dirty, Cleaning 25,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

