



**BMW 3: 1GC514**

Vinnnumber:	<b>WBA3E11060J726102</b>	Versionname:	<b>3 BER 320dA Eff.Dynamics Ed.163PK Aut.</b>
First Registrationdate:	<b>2/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>73623</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1710</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 0 mm</b>	Fr.R.	<b>Michelin: 0 mm</b>
	Re.L.	<b>Michelin: 0 mm</b>	Re.R.	<b>Michelin: 0 mm</b>

**Assistance equipment**

Compressor	<b>Yes</b>
------------	------------

Total cost ex VAT	<b>665,80</b>
-------------------	---------------

Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>308,20</b>
---	---------------



Door R R, Bump(s), PDR - Knock out without painting	<b>82,80</b>
---	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

*No pictures to display*

Wing F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*