



| | | | |
|-----------------------------------|--------------------------|--------------|-------------------------------|
| VOLKSWAGEN Sharan: 1FMB382 | | | |
| Vinnnumber: | WVWZZZ7NZEV007353 | Versionname: | SHARAN Comfortline BMT |
| First Registrationdate: | 13/08/2013 | Fiscalpower: | 115PK |
| Expertise Mileage: | 76396 | Power Kw: | 85 |
| Bodytype: | MPV | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2323 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | |
|--------------------------------|------------------------------|
| Options | |
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Autom climate control |


| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 215/60/16/99 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

| | |
|---|---------|
| Assistance equipment | |
| Total cost ex VAT | 1947,86 |
| Roof, Chemical polution, LI - Repair and paint (complete) | 481,50 |

| | |
|---|--------|
| | |
| Door F L, Scratch(es), LI - Repair and paint (complete) | 318,35 |

| | |
|---|--------|
| | |
| Wing F R, Scratch(es), LI - Repair and paint (complete) | 220,18 |



| | |
|---|--------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|



| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) | 397,68 |
|---|--------|



| | |
|-------------------------------|------|
| Wing F L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|---|------|
| Front bumper, Damaged, Le - Replace and paint | 0,00 |
|---|------|

