


**OPEL Astra: 1EHZ714**

Vinnnumber:	<b>WOLPE6EW0DG042308</b>	Versionname:	<b>ASTRA BER ecoFLEX Cosmo St/St 110PK</b>
First Registrationdate:	<b>10/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>159305</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1523</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/50/17/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>703,48</b>
-------------------	---------------

Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>115,56</b>
---	---------------



Bonnet, Bump(s), Acceptable	<b>0,00</b>
-----------------------------	-------------

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Floor covering F L, Hole, Smart repair 64,32



Interior, Dirty, Cleaning 100,00



Front bumper, Damaged, LI - Repair and paint (complete) 211,80

