



**SKODA Fabia: XN9538**

Vinnnumber:	<b>TMBJK25JXE3076052</b>	Versionname:	<b>FABIA COMBI Ambition</b>
First Registrationdate:	<b>8/12/2015</b>	Fiscalpower:	<b>DPF 75PK</b>
Expertise Mileage:	<b>132124</b>	Power Kw:	<b>55</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>1522</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>185/55/15/82 T Steel</b>			
Winter tyres:	Fr.L.	<b>Fulda: 6 mm</b>	Fr.R.	<b>Fulda: 6 mm</b>
	Re.L.	<b>Fulda: 5 mm</b>	Re.R.	<b>Fulda: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>0,00</b>
-------------------	-------------

Windscreen, Crack, E - Replace	<b>0,00</b>
--------------------------------	-------------



Bodywork, Not original part, Remove lettering	<b>0,00</b>
---	-------------



Phone/Car Kit, Not original part, P - Check	<b>0,00</b>
---	-------------



Bumper R, Damaged, Acceptable 0,00

