



RENAULT Clio: 1GDR194			
Vinnumber:	<b>VF15R040H50049152</b>	Versionname:	<b>CLIO IV BER Expression</b>
First Registrationdate:	<b>9/01/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>31782</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2104</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunction	Rear parking sensors
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>185/65/15/88 T Steel</b>			
Winter tyres:	Fr.L.	<b>Firestone: 4 mm</b>	Fr.R.	<b>Firestone: 4 mm</b>
	Re.L.	<b>Firestone: 5 mm</b>	Re.R.	<b>Firestone: 5 mm</b>

Assistance equipment			
Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT	<b>280,44</b>		
Outer door handle F L, Missing, E - Replace	<b>15,00</b>		



Wheel cover R L, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Door R R, Bad repair, Acceptable	<b>0,00</b>
----------------------------------	-------------



Wheel cover F R, Damaged, E - Replace

24,00



Wheel cover F L, Scratch(es), E - Replace

24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover R R, Scratch(es), E - Replace

24,00



Seat cover F L, Deformed, P - Check

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display